

NOTE: Cut the pad between VUSB and VIN on both Teensy 4.0  
 Ethernet connection from Switch to Sidescan-sonar and RPi  
 USB between teensy ans RPi

