



NOTE: Cut the pad between USB and VIN on both Teensy 4.0

USB between teensy ans RPi

Ethernet connection from Switch to Sidescan-sonar and RPi

